

AD-A101 353

CORPS OF ENGINEERS BUFFALO N Y BUFFALO DISTRICT
FLOOD INSURANCE STUDY, GARFIELD HEIGHTS, OHIO. (U)


MAY 71

F/6 5/3

UNCLASSIFIED

[1 of]
4
AD-A101 353

NL



END
DATE
FILED
8-8-81
DTIC


LEVEL 4 (D)
B-S

FLOOD INSURANCE STUDY

GARFIELD HEIGHTS

OHIO

AD A101353



A

PREPARED FOR THE
FEDERAL INSURANCE ADMINISTRATION

BY THE

DEPARTMENT OF THE ARMY
BUFFALO DISTRICT, CORPS OF ENGINEERS
BUFFALO, NEW YORK 14207

MAY 1971

This document has been approved
for public release and sale; its
distribution is unlimited.

817 10 08?

FILE COPY

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
		AD-A101353
4. TITLE (and Subtitle)	5. TYPE OF REPORT & PERIOD COVERED	
Flood Insurance Study, Garfield Heights Ohio	Final report	
7. AUTHOR(s)	6. PERFORMING ORG. REPORT NUMBER	
9. PERFORMING ORGANIZATION NAME AND ADDRESS	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS	
U.S. Army Engineer District, Buffalo 1776 Niagara Street Buffalo, New York 14207	14 101 71	
11. CONTROLLING OFFICE NAME AND ADDRESS	12. REPORT DATE	
U.S. Army Engineer District, Buffalo 1776 Niagara Street Buffalo, New York 14207	1971	
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)	13. NUMBER OF PAGES	
	40 14371	
16. DISTRIBUTION STATEMENT (of this Report)	15. SECURITY CLASS. (of this report)	
Distribution Unlimited		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number)		
Floods Flooding Garfield Heights		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number)	Garfield Heights encompasses an area approximately four square miles and has a population of about 41,500 people. Mill Creek, Wolf Creek, Andover Creek and their tributaries provide drainage for most of the city. The city has a history of periodic flooding from these streams and also significant flooding from local runoff accumulation and ponding which enters have been taken by the city government to alleviate the various flood problems by providing a system of open and subsurface drains. However, these measures have only a partial effect on the local runoff that would be produced	

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

cont during the 100 and 500 year floods. Hilly terrain, lack of a complete drainage system, a combined storm and sanitary sewer system in some locations, lengthy culverts, are the main reasons for the flooding problems.

FLOOD INSURANCE STUDY
GARFIELD HEIGHTS, OHIO

<u>Paragraph No.</u>	<u>CONTENTS</u>	<u>Page</u>
1	Authority for Study	1
2	Financing of Study	1
3	Description of the Area	1-2
4	Description of Work	2-4
	a. Hydrologic Studies	3
	b. Structure and Content Classification	3
	c. Depth - Damage Relationship Development	3
	d. Elevation - Frequency Relationship Development	3-4
	e. Reaches and Zones	4

EXHIBITS

<u>Number</u>	<u>Page</u>	
1	Structure and Content Designations	5
2-15	Depth - Damage Relationship	6-19
16	Depth - Percent Damage Data	20-23
17-28	Elevation - Frequency Curve	24-35

PLATES Number

Profiles	<i>J</i>
Mill Creek	1-2
Wolf Creek	3
Zone Maps	4-6



FLOOD INSURANCE STUDY
GARFIELD HEIGHTS, OHIO

1. AUTHORITY FOR STUDY

This study was prepared at the request of the Federal Insurance Administration, U.S. Department of Housing and Urban Development, in accordance with the National Flood Insurance Act, Public Law 90-448, dated 1 August 1968, and subsequent criteria. This study provides data required for a Type-10 study in Garfield Heights, Ohio. Flood insurance rates for Garfield Heights will be developed, using data contained in this report, by the Federal Insurance Administration. Authority for the Buffalo District to prepare this study is provided by letter from the Office of the Chief of Engineers, ENGCW-PF, subject: Type-10 Flood Insurance Studies, dated 23 December 1970.

2. FINANCING OF STUDY

This study was financed by the Federal Insurance Administration by reimbursement of funds to the Corps of Engineers (Inter-Agency Agreement (IAA) - H - 8 - 71, Project Order No. 8).

3. DESCRIPTION OF THE AREA

Garfield Heights is an incorporated city within Cuyahoga County.

The City encompasses an area of approximately four square miles and has a population of about 41,500 people. Mill Creek, Wolf Creek, Andover Creek and their tributaries provide drainage for most of the city. The City has a history of periodic flooding from these streams and also significant flooding from local runoff accumulation and ponding which enters into residences through sewers. Some measures have been taken by the city government to alleviate the various flood problems by providing a system of open and subsurface drains. However, these measures have only a partial effect on the local runoff that would be produced during the 100- and 500-year floods. Hilly terrain, lack of a complete drainage system, a combined storm and sanitary sewer system in some locations, local restrictive obstructions, such as walls and lengthy culverts, are the main reasons for the flooding problems. The best method to prevent flood damage to future development in the study area would be to restrict first floor elevations to above flood levels and to develop a system of separate sanitary and storm sewers.

4. DESCRIPTION OF WORK

The work performed in producing the information and data contained in this report is in accordance with the criteria set forth in the "Guidelines for Flood Insurance Studies" published by the Corps of Engineers in January 1970 and subsequent directives.

a. Hydrologic Studies - The frequency of flood stages for the study area was developed from discharge - frequency relationships based on hydrologic studies by the Corps of Engineers.

b. Structure and Content Classification - Symbol designation and procedures used in this study are in accordance with those recommended by the Federal Insurance Administration. These designations are listed in Exhibit 1.

c. Depth - Damage Relationship Development - Depth-damage relationships were developed by determining average house criteria for the various structure and content designations considered as representative of the study area. Content and structural damage were estimated for the various levels of flooding. Damage estimates were based on observed and computed damage information already on file in the Buffalo District Office. Exhibits 2 through 16 show the depth-damage relationships in both tabular and graphical form.

d. Elevation-Frequency Relationship Development - Utilizing hydrologic data, U.S. Geological Survey maps, Cuyahoga County, Ohio, Sanitary Engineering Department topographic maps and field investigations elevation-frequency relationships were determined for seven index points on Mill Creek and five index points on

Wolf Creek. This information was plotted as a smooth curve at each index point as shown on Exhibits 17 through 28. Also shown on these exhibits is the flood hazard factor which most closely resembles each elevation frequency curve as shown in the Federal Insurance Administration publication dated September 1970. A profile indicated the 500-year flood, Base Flood, 10-year flood and the approximate ground elevations for Mill Creek and Wolf Creek are shown on plates 1 through 3.

e. Reaches and Zones - The flood zones were delineated by first determining the overflow limits for the desired flood and then extending the zone to the higher verifiable line, such as a street or bluff line, when possible. When physical boundaries were not available the zone limit is dimensioned from the nearest physical location. The study area consists primarily of an "A" zone, which is subject to flooding by the Base Flood. A "B" zone, which is the area subject to flooding by the 500-year flood but not the base flood, is not shown on the zone maps as the horizontal distance is not significant. The area in the "C" zone shown does not have an apparent flood problem. The "CB" zones shown do have apparent flood problems but a flood hazard factor was not determined. The zone maps for Garfield Heights are shown on plates 4 through 6.

EXHIBIT 1


CLASSES OF STRUCTURES AND CONTENTS

Class of Structure Designations


Kind or Type of Structure <u>1-4 Families</u>	<u>Basement</u>
1 (One Story)	B (Basement)
2 (Two Stories)	N (No Basement)
3 (Split Level)	
4 (Mobile home on foundation)	

CLASS OF CONTENTS DESIGNATION


F (All on first floor)
S (All on second floor)
FS (On first and second floor)
B (All in basement)
BF (Basement and first floor)
BFS (Basement, first and second floor)
TN (Split level without basement)
TB (Split level with basement)
M (Mobile home on foundation)




DEPTH - PERCENT DAMAGE CURVE




DEPTH - PERCENT DAMAGE CURVE




DEPTH - PERCENT DAMAGE CURVE




DEPTH - PERCENT DAMAGE CURVE




DEPTH - PERCENT DAMAGE CURVE




DEPTH - PERCENT DAMAGE CURVE




DEPTH - PERCENT DAMAGE CURVE




DEPTH - PERCENT DAMAGE CURVE




DEPTH - PERCENT DAMAGE CURVE




DEPTH - PERCENT DAMAGE CURVE




DEPTH - PERCENT DAMAGE CURVE



DEPTH - PERCENT DAMAGE CURVE



DEPTH - PERCENT DAMAGE CURVE



DEPTH - PERCENT DAMAGE CURVE

EXHIBIT 16
DEPTH-PERCENT DAMAGE DATA

STRUCTURE

Depth in feet	<u>CLASS</u>					
	1N	1B	2N	2B	3N	3B
-8.0	0.0		0.0		0.0	
-7.5		1.1		0.4		0.4
-7.0		2.0		0.8		0.8
-6.5		2.8		1.0		1.0
-6.0		3.6		1.2		1.2
-5.5		4.2		1.3		1.4
-5.0		4.8		1.5		1.6
-4.5		5.2		1.7		1.9
-4.0		5.6		1.9	0.0	2.5
-3.5		5.9		2.0	3.8	3.5
-3.0		6.2		2.1	5.7	4.8
-2.5		6.5		2.2	7.1	5.8
-2.0	0.0	6.8	0.0	2.5	8.2	6.3
-1.5	0.8	7.0	0.3	3.0	9.1	7.0
-1.0	1.4	7.5	1.0	3.7	10.1	8.0
-0.5	2.5	8.3	1.9	4.6	11.4	9.4
0.0	4.3	10.0	3.0	5.9	13.5	11.7
0.5	9.1	13.1	4.8	7.5	17.1	14.5
1.0	17.0	17.0	6.9	9.6	19.3	17.1
1.5	22.0	20.0	9.5	11.9	20.9	18.9
2.0	25.7	22.3	13.0	14.3	22.0	20.2
2.5	28.8	24.2	16.6	16.6	23.1	21.4
3.0	31.6	25.8	19.9	18.3	24.3	22.6
3.5	34.0	27.2	22.3	19.6	25.6	24.3
4.0	36.3	28.5	24.5	20.7	27.8	26.9
4.5	38.2	29.7	26.3	21.7	31.5	30.2
5.0	40.2	30.7	28.0	22.5	34.8	33.1
5.5	42.0	31.7	29.2	23.5	37.0	35.2
6.0	43.7	32.8	30.5	24.5	39.0	36.8
6.5	45.2	34.1	31.5	25.8	40.3	38.2
7.0	46.8	35.7	32.5	27.4	41.4	39.5
7.5	48.9	37.9	33.7	29.3	42.4	40.6
8.0	51.7	40.7	35.8	31.8	44.6	42.7
8.5	54.0	42.7	39.0	34.1	47.1	45.2
9.0	55.7	44.2	43.0	36.5	48.8	47.6
9.5	56.9	45.3	47.1	38.3	50.0	49.0
10.0	57.9	46.1	50.2	39.7	50.8	50.0
10.5	58.4	46.8	52.6	40.8	51.6	50.8
11.0	58.9	47.3	54.2	41.8	52.3	51.5
11.5	59.0	47.8	55.5	42.6	53.1	52.2
12.0	59.0	48.0	56.6	43.2	54.0	53.0
12.5			57.4	43.9	55.4	54.0
13.0			58.3	44.3	57.3	55.6
13.5			59.0	44.8	59.6	57.0
14.0			59.5	45.1	61.2	58.0
14.5			60.0	45.5	62.3	58.7
15.0			60.5	45.9	63.2	59.3
15.5			61.2	46.4	63.8	59.7

EXHIBIT 16 (Con't)
DEPTH-PERCENT DAMAGE DATA

STRUCTURE

Depth in feet	CLASS					4
	1N	1B	2N	2B	3N	
16.0			62.1	47.3	64.2	60.0
16.5			63.3	49.0	64.3	60.3
17.0			65.0	51.3	64.4	60.5
17.5			67.0	53.2		
18.0			68.4	54.7		
18.5			68.8	55.7		
19.0			69.0	56.3		
19.5			69.1	56.9		
20.0			69.2	57.2		
20.5			69.3	57.6		
21.0			69.4	57.8		

EXHIBIT 16 (Con't)
DEPTH-PERCENT DAMAGE DATA


CONTENTS

<u>Depth in feet</u>	<u>F</u>	<u>BF</u>	<u>FS</u>	<u>CLASS BFS</u>	<u>TN</u>	<u>TB</u>	<u>M</u>
-8.0		0.0		0.0		0.0	
-7.5		2.8		1.7		0.9	
-7.0		4.8		2.9		1.3	
-6.5		6.3		3.9		1.6	
-6.0		7.7		4.7		1.9	
-5.5		8.8		5.3		2.0	
-5.0		9.8		6.0		2.1	
-4.5		10.7		6.5		2.7	
-4.0		11.4		7.0	0.0	3.6	
-3.5		12.2		7.5	5.2	5.2	
-3.0		12.9		8.0	8.8	7.2	
-2.5		13.3		8.4	11.3	9.0	
-2.0		14.0		8.8	13.3	10.7	
-1.5		14.7		9.2	15.0	12.0	
-1.0		15.7		9.7	16.8	13.0	
-0.5		17.0		10.2	18.5	14.0	
0.0	0.0	18.8	0.0	12.0	20.7	15.3	0.0
0.5	6.0	21.0	9.0	15.0	24.2	18.2	13.5
1.0	15.0	24.1	15.5	19.5	29.5	23.7	26.0
1.5	28.5	29.0	21.0	25.5	34.2	29.0	37.0
2.0	40.0	43.5	25.3	31.0	37.3	32.9	46.5
2.5	48.7	55.2	29.0	35.3	39.6	35.3	54.3
3.0	55.7	62.5	32.0	39.0	41.3	37.3	61.0
3.5	61.2	67.6	34.5	42.2	43.0	39.0	66.3
4.0	65.9	71.5	36.9	45.1	44.7	40.6	71.0
4.5	69.5	74.4	39.0	47.4	46.6	42.3	74.9
5.0	72.8	77.0	40.8	49.4	48.9	44.3	78.2
5.5	75.5	78.7	42.5	51.0	52.6	47.0	81.2
6.0	77.8	80.0	44.2	52.3	59.1	51.0	83.6
6.5	79.6	80.9	45.7	53.4	64.9	56.0	85.7
7.0	81.1	81.3	47.2	54.5	69.0	61.3	87.6
7.5	82.4	81.6	48.6	55.4	72.0	65.5	89.0
8.0	83.3	81.7	50.0	56.4	74.3	69.0	89.8
8.5	83.9	81.8	51.5	57.7	76.1	71.9	89.9
9.0	84.0	81.9	53.6	59.3	77.4	74.0	89.9
9.5	84.1	81.9	56.5	61.5	78.5	75.6	89.9
10.0	84.2	82.0	61.5	64.9	79.6	77.0	89.9
10.5	84.3	82.0	66.5	68.5	80.3	78.1	

EXHIBIT 16 (Con't)
DEPTH-PERCENT DAMAGE DATA

CONTENTS

Depth in feet	F	BF	FS	<u>CLASS</u>			M
				BFS	TN	TB	
11.0	84.3	82.0	70.7	71.9	81.0	79.2	
11.5	84.4	82.0	73.6	74.6	81.5	80.1	
12.0	84.4	82.0	75.8	77.0	82.0	80.9	
12.5			77.6	78.7	82.3	81.5	
13.0			79.0	79.9	82.6	81.8	
13.5			80.2	80.8	82.8	81.8	
14.0			81.3	81.6	82.9	81.8	
14.5			82.0	82.1	83.0	81.8	
15.0			82.7	82.6	83.0	81.8	
15.5			83.1	83.0	83.0	81.8	
16.0			83.5	83.2	83.0	81.8	
16.5			83.8	83.4	83.0	81.8	
17.0			83.9	83.6	83.0	81.8	
17.5			84.0	83.7			
18.0			84.0	83.8			
18.5			84.0	83.9			
19.0			84.0	84.0			
19.5			84.0	84.0			
20.0			84.0	84.0			
20.5			84.0	84.0			
21.0			84.0	84.0			




NOTES:

1 CURVE CORRESPONDS TO FLOOD HAZARD FACTOR NUMBER 020A
2 CURVE DEVELOPED FOR INDEX NUMBER 1 MILE 3.45

PLOTTING DATA	
FREQUENCY YEARS	FLOOD ELEVATION
SPF	
500	794.5
100	793.5
25	
10	791.4

FLOOD INSURANCE STUDY
GARFIELD HEIGHTS, OHIO
MILL CREEK
ELEVATION FREQUENCY
RELATIONSHIP
CORPS OF ENGINEERS, U.S. ARMY
BUFFALO, NEW YORK, DISTRICT
PREPARED FOR
FEDERAL INSURANCE ADMINISTRATION
MAY 1971




NOTES:

1. CURVE CORRESPONDS TO FLOOD HAZARD FACTOR NUMBER .035A
2. CURVE DEVELOPED FOR INDEX NUMBER .2 MILE 3.65

PLOTTING DATA	
FREQUENCY YEARS	FLOOD ELEVATION
SPF	
500	801.6
100	800.0
25	
10	796.7

FLOOD INSURANCE STUDY
GARFIELD HEIGHTS, OHIO
MILL CREEK
**ELEVATION FREQUENCY
RELATIONSHIP**
CORPS OF ENGINEERS, U.S. ARMY
BUFFALO, NEW YORK, DISTRICT
PREPARED FOR
FEDERAL INSURANCE ADMINISTRATION
MAY 1971




NOTES:

- 1 CURVE CORRESPONDS TO FLOOD HAZARD FACTOR NUMBER .025A
- 2 CURVE DEVELOPED FOR INDEX NUMBER 3 MILE 3.85

PLOTTING DATA	
FREQUENCY YEARS	FLOOD ELEVATION
SPF	
500	806.7
100	805.4
25	
10	803.1

FLOOD INSURANCE STUDY
GARFIELD HEIGHTS, OHIO
MILL CREEK
**ELEVATION FREQUENCY
RELATIONSHIP**
CORPS OF ENGINEERS, U.S. ARMY
BUFFALO, NEW YORK, DISTRICT
PREPARED FOR
FEDERAL INSURANCE ADMINISTRATION
MAY 1971




NOTES:

1 CURVE CORRESPONDS TO FLOOD HAZARD FACTOR NUMBER .0308
2 CURVE DEVELOPED FOR INDEX NUMBER .4 MILE 4.05

PLOTTING DATA	
FREQUENCY YEARS	FLOOD ELEVATION
SPF	
500	812.4
100	810.7
25	
10	807.5

FLOOD INSURANCE STUDY
GARFIELD HEIGHTS, OHIO
MILL CREEK
ELEVATION FREQUENCY
RELATIONSHIP
CORPS OF ENGINEERS, U.S. ARMY
BUFFALO, NEW YORK, DISTRICT
PREPARED FOR
FEDERAL INSURANCE ADMINISTRATION
MAY 1971




NOTES:

1. CURVE CORRESPONDS TO FLOOD HAZARD FACTOR NUMBER .030A
2. CURVE DEVELOPED FOR INDEX NUMBER 5-MILE 4.50

PLOTTING DATA	
FREQUENCY YEARS	FLOOD ELEVATION
SPF	
500	824.4
100	823.0
25	
10	819.8

FLOOD INSURANCE STUDY
GARFIELD HEIGHTS, OHIO
MILL CREEK
**ELEVATION FREQUENCY
RELATIONSHIP**
CORPS OF ENGINEERS, U.S. ARMY
BUFFALO, NEW YORK, DISTRICT
PREPARED FOR
FEDERAL INSURANCE ADMINISTRATION
MAY 1971




NOTES:

1. CURVE CORRESPONDS TO FLOOD HAZARD FACTOR NUMBER .020A
2. CURVE DEVELOPED FOR INDEX NUMBER .6-MILE 4.80

PLOTTING DATA	
FREQUENCY YEARS	FLOOD ELEVATION
SPF	
500	832.6
100	831.6
25	
10	829.8

**FLOOD INSURANCE STUDY
GARFIELD HEIGHTS, OHIO
MILL CREEK**
**ELEVATION FREQUENCY
RELATIONSHIP**
 CORPS OF ENGINEERS, U.S. ARMY
 BUFFALO, NEW YORK, DISTRICT
 PREPARED FOR
 FEDERAL INSURANCE ADMINISTRATION
 MAY 1971




NOTES:

1 CURVE CORRESPONDS TO FLOOD HAZARD FACTOR NUMBER 025C
2 CURVE DEVELOPED FOR INDEX NUMBER 7-MILE 5.10

PLOTTING DATA	
FREQUENCY YEARS	FLOOD ELEVATION
SPF	
500	839.9
100	837.9
25	
10	835.6

FLOOD INSURANCE STUDY
GARFIELD HEIGHTS, OHIO
MILL CREEK
ELEVATION FREQUENCY
RELATIONSHIP
CORPS OF ENGINEERS, U.S. ARMY
BUFFALO, NEW YORK, DISTRICT
PREPARED FOR
FEDERAL INSURANCE ADMINISTRATION
MAY 1971




NOTES:

1. CURVE CORRESPONDS TO FLOOD HAZARD FACTOR NUMBER .005D
2. CURVE DEVELOPED FOR INDEX NUMBER 1-400 FEET

PLOTTING DATA	
FREQUENCY YEARS	FLOOD ELEVATION
SPF	
500	816.0
100	817.1
25	
10	816.6

FLOOD INSURANCE STUDY
GARFIELD HEIGHTS, OHIO
WOLF CREEK
**ELEVATION FREQUENCY
RELATIONSHIP**
CORPS OF ENGINEERS, U.S. ARMY
BUFFALO, NEW YORK, DISTRICT
PREPARED FOR
FEDERAL INSURANCE ADMINISTRATION
MAY 1971



NOTES:


1. CURVE CORRESPONDS TO FLOOD HAZARD FACTOR NUMBER .0108
2. CURVE DEVELOPED FOR INDEX NUMBER .2-1400 FEET

PLOTTING DATA	
FREQUENCY YEARS	FLOOD ELEVATION
SPF	
500	830.1
100	829.5
25	
10	828.3

FLOOD INSURANCE STUDY
GARFIELD HEIGHTS, OHIO
WOLF CREEK

ELEVATION FREQUENCY
RELATIONSHIP

CORPS OF ENGINEERS, U.S. ARMY
BUFFALO, NEW YORK, DISTRICT
PREPARED FOR
FEDERAL INSURANCE ADMINISTRATION
MAY 1971




NOTES:

1 CURVE CORRESPONDS TO FLOOD HAZARD FACTOR NUMBER. 010D
2 CURVE DEVELOPED FOR INDEX NUMBER 3-2800 FEET

PLOTTING DATA	
FREQUENCY YEARS	FLOOD ELEVATION
SPF	
500	851.8
100	850.5
25	
10	849.4

FLOOD INSURANCE STUDY
GARFIELD HEIGHTS, OHIO
WOLF CREEK
ELEVATION FREQUENCY
RELATIONSHIP
CORPS OF ENGINEERS, U.S. ARMY
BUFFALO, NEW YORK, DISTRICT
PREPARED FOR
FEDERAL INSURANCE ADMINISTRATION
MAY 1971




NOTES:

1 CURVE CORRESPONDS TO FLOOD HAZARD FACTOR NUMBER .005D
2 CURVE DEVELOPED FOR INDEX NUMBER 4-3800 FEET

PLOTTING DATA	
FREQUENCY YEARS	FLOOD ELEVATION
SPF	
500	863.0
100	861.2
25	
10	859.6

FLOOD INSURANCE STUDY
GARFIELD HEIGHTS, OHIO
WOLF CREEK
ELEVATION FREQUENCY
RELATIONSHIP
CORPS OF ENGINEERS, U.S. ARMY
BUFFALO, NEW YORK, DISTRICT
PREPARED FOR
FEDERAL INSURANCE ADMINISTRATION
MAY 1971





NOTES:


1 CURVE CORRESPONDS TO FLOOD HAZARD FACTOR NUMBER .030C
2 CURVE DEVELOPED FOR INDEX NUMBER 5-4600 FEET

PLOTTING DATA	
FREQUENCY YEARS	FLOOD ELEVATION
SPF	
500	871.2
100	868.8
25	
10	865.7

FLOOD INSURANCE STUDY
GARFIELD HEIGHTS, OHIO
WOLF CREEK
ELEVATION FREQUENCY
RELATIONSHIP
CORPS OF ENGINEERS, U.S. ARMY
BUFFALO, NEW YORK, DISTRICT
PREPARED FOR
FEDERAL INSURANCE ADMINISTRATION
MAY 1971







LEGEND:

- - - - 500 YEAR FLOOD
- - - 100 YEAR FLOOD
- - - 10 YEAR FLOOD
- APPROXIMATE STREAMBED
- APPROXIMATE FLOOR
- APPROXIMATE LOW
- △ INDEX POINT

NOTES:

CREST PROFILES ARE BASED ON THE FOLLOWING:

1. EXISTING CHANNEL CONDITIONS
2. EXISTING STRUCTURES
3. EXISTING CONDITIONS ON THE STREAMBED

LARGE SCALE FILLING WILL NOT OCCUR UNLESS SUFFICIENT FLOODWAY

FLOOD INSURANCE RATE MAP
GARFIELD HILL
PROPERTY


U.S. ARMY ENGINEER
MAY 1982


LOOD
OOD
OOD
E STREAM BED
E FLOOR ELEVATION
E LOW STEEL ELEVATION
T


RE BASED ON THE
NEL CONDITIONS
CTURES
ITIONS OF DEVELOPMENT.
ING WILL RAISE PROFILES
OODWAY IS PROVIDED.

D INSURANCE STUDY
FIELD HEIGHTS, OHIO
MILL CREEK
PROFILES
ENGINEER DISTRICT, BUFFALO
MAY 1971

(4 PLATE I







855

850

845

840

835

825

820

815

810

MC CRACKEN ROAD BR.

WESTERN RAILWAY

FLOOD INSURANCE
GARFIELD HILL
MILL CREEK
PROFILE


U.S. ARMY ENGINEER
MAY 19

DD
D

STREAM BED
FLOOR ELEVATION
LOW STEEL ELEVATION

BASED ON THE
L CONDITIONS
URES
ONS OF DEVELOPMENT
WILL RAISE PROFILES
DWAY IS PROVIDED.

INSURANCE STUDY
ED HEIGHTS, OHIO
MILL CREEK
PROFILES
ENGINEER DISTRICT, BUFFALO
MAY 1971



GARFIELD

3

2

ZONE A2

ZONE A3


16


20

24


28

GOLF CREEK FROM MOUTH IN HUNDREDS OF FEET






LOOD INSURANCE STUDY
ARFIELD HEIGHTS, OHIO
WOLF CREEK
PROFILES
ARMY ENGINEER DISTRICT, BUFFALO
MAY 1971



F

STREET INDEX

ALEXANDER RD	D3	GARFIELD BLVD	CN, DN, EN
AYNDALE AVE	B5	GRAND DIVISION AVE	BS, CS
BANCHETT AVE	B5	GRANGER RD	B1
BANG DR	C3	GREEN DR	B4
BIRCHWOOD RD	CW, DN	GREENVIEW AVE	DN, EN
BLYNTHORN RD	B4	HOMECREST AVE	EN
BOWLING RD	D5	HORTON RD	B4
BORGES	D5	JEFFRIES AVE	B5
BROADWAY	E5	JOLIET RD	E5
BRUNSWICK AVE	F1	LANGTON AVE.	E3, F3
BURLEIGH RD	B4	LINCOLN AVE.	F2
CANAL RD	A2	MC CRACKEN BLVD	D2, E3, F3
CARDWELL	E5	MIDWEST AVE	C2
CARE DR	C3	MOUNTVIEW AVE	E1
CHIDESTER DR	B4	OLD GRANGER RD	B2, D1, E1
DANBURY AVE	F1	PARK HEIGHTS AVE.	D2, E3, F3
DAVID RD	D3	PARK VIEW AVE.	D4
DELL DR	C2	PENFIELD AVE	E2
DUNCAN DR	C2, CN	PLYMOUTH AVE	D3, E2, F3
DOROTHY AVE	CW	RAYMOND	E1
EAST 81 ST.	B3, B4	REED AVE.	C3
EAST 83 ST.	C3, CN	ROBINSON AVE.	D5
EAST 85 ST.	C3, CN	RICHLAND AVE.	E4
EAST 86 ST.	C3, CN	ROCKWOOD RD.	B4
EAST 88 ST.	C2, C2, CN	ROSEWOOD AVE.	B5
EAST 90 ST.	C3, CN	RUNNymeade	EN
EAST 92 ST.	D3, DN	RUSSEL AVE.	E4
EAST 94 ST.	D3, DN, D5, D2	SLADDEN AVE.	D5
EAST 96 ST.	D3, DN	SOUTH HIGHLAND	E2
EAST 98 ST.	D3, D4, D1	SUMMERDALE	E3
EAST 100 ST.	D4	THORTON AVE.	F2
EAST 102 ST.	E2	TONSING DR.	F1
EAST 104 ST.	E2, E5	TURNEY RD.	EN
EAST 106 ST.	E2	VERNON AVE.	E3, F3
EAST 107 ST.	E3, EN	VINEYARD AVE.	B5
EAST 108 ST.	E3, EN	VISTA AVE.	B4
EAST 109 ST.	E3, FN	WADSWORTH AVE.	E3, F3
EAST 110 ST.	F1, F3, FN	WALLINGFORD AVE.	F2
EAST 111 ST.	F2	WARNER RD.	B2
EAST 112 ST.	F2		
EAST 113 ST.	F2		
EAST 114 ST.	F2		
EAST 115 ST.	F2		
EDGE PARK DR.	EN, FN, F3		
ELMWOOD AVE.	E2		
ENFIELD	F1		

LEGEND:

- LIMITS OF ZONES
- GARFIELD HEIGHTS CITY LIMITS
- 805 — 100-YEAR FLOOD ELEVATION REFERENCE LINE
- (4) DISTANCE FROM MOUTH IN MILES
- 1000' DISTANCE FROM MOUTH IN FEET

NOTE:

FLOOD INSURANCE STUDY MAP WAS PREPARED FOR THE FEDERAL INSURANCE ADMINISTRATION.


**FLOOD INSURANCE STUDY
GARFIELD HEIGHTS, OHIO
FLOOD INSURANCE STUDY MAP**

U.S. ARMY ENGINEER DISTRICT, BUFFALO

MAY 1971

F

PLATE 4



E

F

STREET INDEX

AVEN AVE	C6	FORESTDALE DR	C6
ANGLOPH BLDG	A5	GARLAND AVE	B3
ASH ST	C4	GRANGER RD	A2 B2
BANUS AVE	B1	HENRY ST	A4 B3
BARTON AVE	D4	HILLSDIDE AVE	C4
BLANCHARD AVE	D4	HOMESTEAD DR	F3
BLASSE AVE	F3	HY COURT	B2
BROADVIEW	A4 C4	LAWRENCE AVE	C4
CENTER AVE	A3	LINN AVE	C1
CHAMBERS ST	A4 B4	MAPLE ROW DR	D2
CHERRY ST	B4	MARPLETON AVE	B6 C6
CHI-STONE AVE	A5 C6	MARGUERITE AVE	A3
CLEARVIEW RD	B3	MARY ANN DR	D2
COOPER DR	C4	MC CRACKEN RD	A3 E3
CRAWDOD DR	C6	MELROSE AVE	B5
CRAWWOOD PARK BLVD	C4 D5	NORTH DR	C6
CREST AVE	A2	OAK ST	B2
DRESSLER AVE	C4	OMIC ST	D4
DRIVEWAY	D4	ORCHARD RD	E3
EAST BLVD	B5	OSBURN RD	D4
EAST 107 ST	A2	OVERLOOK RD	B3 B4
EAST 119 ST	A2	PARK KNOLL DR	B3
EAST 120 ST	A1	PARKWAY DR	A3
EAST 121 ST	A1	PLATEAU DR	F3
EAST 122 ST	B1	REINDEER AVE	B3
EAST 124 ST	B1	REDWOOD AVE	B5 C5
EAST 126 ST	B2 B5	ROLAND DR	C1
EAST 128 ST	B2	ROSALIE DR	D2
EAST 129 ST	B1	ROYAL BLVD	C1
EAST 131 ST	B4 C4 C2 C5	ST. CLAREMONT	B2
EAST 132 ST	C1	SAYBROOK AVE	C5
EAST 133 ST	C2	SERVICE CT	B6
EAST 134 ST	C1	SILVER RD	B2 C2
EAST 136 ST	C1 C4	SOUTHERN AVE	B3
EAST 138 ST	C5	SOUTH PARKWAY DR	B6 C6
EAST 139 ST	C2	THORNHURST AVE	B6
EAST 140 ST	D5	TORNING DR	A1
EAST 141 ST	D3	WALLINGFORD AVE	A2 C2
EAST 142 ST	D4		
EAST 144 ST	D4		
EAST 145 ST	D4		
EAST 146 ST	D4		
EAST 147 ST	D4		
EAST 148 ST	D4		
EAST 149 ST	D4		
EAST 150 ST	D3		
EDGE PARK DR	A3		
ELMWOOD AVE	A2		
EVELYN DR	D2		


6

5

4

3

2

LEGEND:

— — — LIMITS OF ZONES

— — — GARFIELD HEIGHTS CITY LIMITS

— 830 — 100-YEAR FLOOD ELEVATION
REFERENCE LINE(5) DISTANCE FROM MOUTH IN MILES
DISTANCE FROM MOUTH IN FEETNOTE:FLOOD INSURANCE STUDY MAP WAS PREPARED
FOR THE FEDERAL INSURANCE ADMINISTRATION.**FLOOD INSURANCE STUDY****GARFIELD HEIGHTS, OHIO****FLOOD INSURANCE STUDY MAP**

U.S. ARMY ENGINEER DISTRICT, BUFFALO


MAY 1971

E

F


2

PLATE 1



E

F

**STREET INDEX**

ANGUER BLVD	C8,C9,D4	JENNY LANE	C6
BENSON AVE	F3	KIMBERLY DR	F2
BRADWELL RD	D6	LILAC AVE	H5
BRANFORD AVE	F2	LINDA LANE	H6
BRIARCLIFFE DR	C5	LITTLETON RD	E4
BROOKHILL DR.	F2	MAPLE LEAF DR. BLVD	F5,E5
CAROL JEAN BLVD	C6	MARTIN DR	F7
CARPENTER RD	E4,F5	MILD RD	F4
CHESTER RD	D5,F6	MONICA LANE	F4
CONTE DR	D6	NEW ROCKSIDE RD	D3
CROFTON RD	D5	OAK PARK BLVD	E6
CUMBERLAND DR	D6	OAK VIEW BLVD	E5
DARLINGTON RD	D6	ORME RD	D4
DERBY RD	D5	PAMELA DR	F2
EAST 94 ST	A6	ROCKCLIFFE AVE.	B6
EAST 122 ST	B6	ROSMOOR DR	F3
EAST 128 ST.	D6	ROCK SIDE RD	D3, D4, E4, F4
EAST 130 ST.	E6	RUDOLPH AVE	B6
EAST 133 ST.	E5	RYBAR AVE	F3
EAST 135 ST.	E6	SATION DR	C6
EAST 138 ST.	F4,F5	SCHREIBER RD.	F1
EAST 139 ST.	F5	SHADY OAK BLVD	E6
EAST 140 ST.	F4	SHADY WAY BLVD	E6
EASTWOOD BLVD	E5	SHERWOOD CIRCLE	E2
EMFIELD	D6	SMLAND AVE	F3
FAIRLAKE BLVD	E5	SUMMIT AVE	I3
FARMINGTON DR	F2	SUNNCLIFFE AVE	B5
FONDHAM RD	D5	SUNSET RD	E3
FOXCROFT DR	F3	THRAVES RD	E5
FRUITSDIDE RD.	E3	TURNEY RD.	D6, E3
GRANNIS RD	D4	UPPER SUNSET RD	E3
GROVE DR	F2	VALLEY LANE	D4
HASTINGS RD	D5	WILLARD AVE	D6
HALLAND AVE	F3	WOODWARD BLVD	E6
HATHWAY RD	E4,F4	YORN BLVD.	E5
HAVANA RD	D4	YORKCLIFFE AVE	B6
HEMPSTEAD RD	D6		
HUNTER DR.	F2		
IRVING AVE	B6		

6

5

4

3

2

NOTE:

FLOOD INSURANCE STUDY MAP WAS PREPARED
FOR THE FEDERAL INSURANCE ADMINISTRATION.

FLOOD INSURANCE STUDY**GARFIELD HEIGHTS, OHIO****FLOOD INSURANCE STUDY MAP**

U.S. ARMY ENGINEER DISTRICT, BUFFALO

MAY 1971

PLATE 6

E

F

2

